

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5





FIG. 6






FIG. 8





FIG. 9



9 / 3 6

FIG. 10




FIG. 11





FIG. 12



12/36

FIG. 13




FIG. 14




FIG. 15






FIG. 16






FIG. 18




FIG. 19





FIG. 20



20/36

FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35





FIG. 36



Yasuo Ohsawa, et al. Q86524
Filed: February 28, 2005
For: PNEUMATIC TIRE AND
TIRE WHEEL ASSEMBLY

36/36

10/526068




FIG. 37

